

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on February 27, 1995.

Darrell M. Pederson,  
Acting Manager, Transport Airplane  
Directorate, Aircraft Certification Service.  
[FR Doc. 95-5244 Filed 3-2-95; 8:45 am]  
BILLING CODE 4910-13-U

## 14 CFR Part 39

[Docket No. 94-NM-241-AD]

### Airworthiness Directives; Fokker Model F28 Mark 0100 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Fokker Model F28 Mark 0100 series airplanes. This proposal would require installation of reinforcement plates at certain fuselage stations. This proposal is prompted by a report indicating that cracks were found in the frame strips at certain fuselage stations on a Model F28 Mark 0100 series airplane test article due to fatigue-related stress. The actions specified by the proposed AD are intended to prevent such fatigue-related cracking, which could result in reduced structural integrity of the fuselage pressure vessel.

**DATES:** Comments must be received by April 28, 1995.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-241-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. -

The service information referenced in the proposed rule may be obtained from Fokker Aircraft USA, Inc., 1199 North Fairfax Street, Alexandria, Virginia 22314. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Tim Dulin, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2141; fax (206) 227-1320.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited -

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received. -

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket. -

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-NM-241-AD." The postcard will be date stamped and returned to the commenter.

##### Availability of NPRMs -

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-241-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

##### Discussion

The Rijksluchtvaartdienst (RLD), which is the airworthiness authority for the Netherlands, recently notified the FAA that an unsafe condition may exist on certain Fokker Model F28 Mark 0100 series airplanes. The RLD advises that, during full-scale fatigue testing on a Model F28 Mark 0100 series airplane test article, cracks were found in the frame strips at fuselage stations 14911 and 17011. The cause of such cracking has been attributed to fatigue-related stress. Such fatigue-related cracking, if not detected and corrected in a timely

manner, could result in reduced structural integrity of the fuselage pressure vessel.

Fokker has issued Service Bulletin SBF100-53-072, dated March 12, 1993, which describes procedures for installation of reinforcement plates at left and right fuselage stations 14911 and 17011. Installation of the reinforcement plates will reduce stress in this area and increase the fatigue life of the affected parts. The RLD classified this service bulletin as mandatory and issued Netherlands airworthiness directive BLA 93-037(A), dated March 17, 1993, in order to assure the continued airworthiness of these airplanes in the Netherlands.

This airplane model is manufactured in the Netherlands and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the RLD has kept the FAA informed of the situation described above. The FAA has examined the findings of the RLD, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require installation of reinforcement plates at left and right fuselage stations 14911 and 17011. The actions would be required to be accomplished in accordance with the service bulletin described previously.

As a result of recent communications with the Air Transport Association (ATA) of America, the FAA has learned that, in general, some operators may misunderstand the legal effect of AD's on airplanes that are identified in the applicability provision of the AD, but that have been altered or repaired in the area addressed by the AD. The FAA points out that all airplanes identified in the applicability provision of an AD are legally subject to the AD. If an airplane has been altered or repaired in the affected area in such a way as to affect compliance with the AD, the owner or operator is required to obtain FAA approval for an alternative method of compliance with the AD, in accordance with the paragraph of each AD that provides for such approvals. A note has been included in this notice to clarify this requirement.

The FAA estimates that 45 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 160 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$3,800 per airplane. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$603,000, or \$13,400 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

Fokker: Docket 94–NM–241–AD.

*Applicability:* Model F28 Mark 0100 series airplanes, serial numbers 11244 through 11371 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent cracking in the frame strips at fuselage stations 14911 and 17011, which could result in reduced structural integrity of the fuselage pressure vessel, accomplish the following:

(a) Prior to the accumulation of 24,000 total flight cycles, or within 6 months after the effective date of this AD, whichever occurs later, install reinforcement plates at left and right fuselage stations 14911 and 17011, in accordance with Fokker Service Bulletin SBF100–53–072, dated March 12, 1993.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM–113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on February 27, 1995.

Darrell M. Pederson,  
Acting Manager, Transport Airplane  
Directorate, Aircraft Certification Service.  
[FR Doc. 95–5243 Filed 3–2–95; 8:45 am]

**BILLING CODE 4310–13–U**

#### **14 CFR Part 39**

[Docket No. 95–NM–05–AD]

#### **Airworthiness Directives; Fokker Model F28 Mark 0100 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Fokker Model F28 Mark 0100 series airplanes. This proposal would require an inspection to determine the adequacy of clearance between the normal maximum (second) detent for the reverse thrust control and the surrounding moving parts and to detect chafing or damage of the detent. This proposal would also require eventual replacement of the normal maximum detent with an improved detent. This proposal is prompted by a report indicating that an inadequate level of clearance between the normal maximum detent and the surrounding parts may exist on earlier production Model F28 Mark 0100 series airplanes. The actions specified by the proposed AD are intended to ensure proper operation of the normal maximum detent for reverse thrust control.

**DATES:** Comments must be received by April 28, 1995.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–103, Attention: Rules Docket No. 95–NM–05–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Fokker Aircraft USA, Inc., 1199 North Fairfax Street, Alexandria, Virginia 22314. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Tim Dulin, Aerospace Engineer, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (206) 227–2141; fax (206) 227–1320.

#### **SUPPLEMENTARY INFORMATION:**

Comments Invited

Interested persons are invited to participate in the making of the